



Roush Performance Products, Inc.
28156 Plymouth Road, Suite Z
Livonia, Michigan 48150

July 24, 2009

Dear Roush Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Roush Performance Products ("Roush") has decided that a defect which relates to motor vehicle safety exists in model year ("MY") 2010 Ford Mustangs manufactured between April 9, 2009 and July 15, 2009 and altered by Roush to include a Sport Brake Kit Option. These vehicles are advertised and sold in the market as the "2010 Roush Stage 1 Mustang", the "2010 Roush Stage 2 Mustang" and the "2010 Roush 427R Mustang" (hereinafter referred to as "2010 ROUSH Vehicles").

Roush has determined that the caliper anchor plate mounting bolts may become loose or dislodged during operation. This failure may result in a loss of stopping performance and, in extreme cases, could result in a crash.

Specifically, on 2010 ROUSH Vehicles equipped with the Sport Brake Kit Option, Roush has installed slotted factory replacement front and rear rotors and red painted factory front and rear calipers on the affected vehicles. Our records indicate that you own one of the affected vehicles.

To remedy this problem, your Ford dealer will remove and replace the front and rear caliper anchor plate mounting bolts on your vehicle, according to the factory replacement procedure. This work will be performed free of charge to you. Please contact your Ford dealer at your earliest convenience in order to make an appointment to have your vehicle repaired. When you call, be prepared to provide your dealer with your name and Vehicle Identification Number. It is essential to make an appointment in advance for this work, so that your dealer can have the replacement kit available for this repair when you bring your car in. Please bring this notice with you when you bring your car to the dealer. We estimate that this repair will take approximately half a business day.

If you no longer own this vehicle, please call Roush at (866)-307-6788 and provide us with the vehicle identification number (VIN) of the vehicle and the name and address of the current owner (if you know them) so we may contact him or her about this recall.

If you believe that Roush has failed or is unable to remedy the defect without charge within a reasonable time, please contact Roush at (866)-307-6788. You may also contact the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you have leased this vehicle to another person, federal regulations require you to send a copy of this notice to your lessee by first-class mail within ten days of your receipt of this notice.

Thank you for your attention to this matter. We apologize for any inconvenience, but your safety is our priority.

Sincerely,

Joseph Thompson
Vice President & General Manager